

TECHNICAL Bulletin 222239



To ensure the most reliable fit and performance of our aftermarket replacement products, Northern Radiator sometimes implements design changes to products to ensure continuity with changing OEM designs. In the case of the 222239, slight design changes were made in order to match recent changes to the OEM product. Customers replacing this product in some older applications may find that the updated design (whether from Northern or the OEM) presents a more snug fit compared to the older design. To make installation easier in these cases, the installer should loosen the radiator frame bolts in all four corners prior to installing the 222239 Charge Air Cooler. This will allow the framework to accept the updated design more easily.

For questions or concerns, please contact your Northern Radiator sales representative or reach out to customer service at 800-328-8900.