


Not All Radiators are Created Equal!

Do you know what you're buying?



Not just an Installation Kit Mounting pin hardware, factory style foam, quick connect & O-ring face seal oil cooler fittings also included. This kit allows one radiator to fit different generations of truck model years.
Fits VNL 2008 & Newer.



SEE HOW NORTHERN RADIATOR COMPARES TO 5 OTHER COMPETITORS' PRODUCTS.

Northern Radiator's mission is to offer a wide range of well-designed, quality-built products, at a fair price, delivered expeditiously. Our research and development team brought in 5 competitors' products to measure against our own. We want to share the results with you. Measuring our **239047** against competitive product in the aftermarket; **we've identified several key characteristics to look for in a quality radiator.**

239047	Northern Radiator	A	B	C	D	E
Corner Supports	Proprietary Bridge Clips	Singular Tube Clips	Bent Singular Tube Clips	Extruded	Bridge Clips	Bridge Clips
Core Thickness	2 1/16"	1 7/8"	1 7/8"	1 7/8"	1 7/8"	2"
Crimps	OEM	Tabbed	Tabbed	Tabbed	OEM	Tabbed
Expansion Joints	Tooled	None	Tooled	Poor Cut	Tooled	Poor Non-Functional
Fittings/Adapters	Yes	None	None	None	None	Yes
Foam Strips	OEM	OEM	Poor	Poor	None	Poor
Hose Connection Reinforcement	Formed Stainless	None	None	Aluminum Tube	Aluminum Tube	Aluminum Tube
OEM Drain Connection	Yes	No	No	No	No	No
Oil Coolers	8-Plate Stainless	6-Plate Aluminum	7-Plate Stainless	6-Plate Aluminum	7-Plate Stainless	5-Plate Stainless
Pin Bushings	Sleeved	None	None	None	None	None
Tank	Fiber Reinforced Plastic	Plastic	Plastic	Plastic	Plastic	Plastic
Mounting Pins Included	Yes	No	No	No	No	No

Be sure you are comparing Radiators to Radiators,
what you get varies from A, B, C, D & E.

Some illustrated
perspectives of
A, B, C, D & E

Inlet & Outlet Reinforcement

Poor fitment, aluminum
tubing, or none at all

Core

1 7/8" - 2" Thick

"THE OTHER GUYS"

Tanks Unknown, poor
plastic composition

Pin Mount Holes

No metal reinforcement

Crimps

Not OEM, failure to use double
crimp strips causes weakness
and failure in corners

Expansion Joints

Poor expansion, some
are cut as an after-
thought, making them
even more weak

Oil Cooler

Varies from 5 to 7
plates in aluminum or
stainless construction

Compare all of this to
what comes in a
Northern Radiator box;
EXPECT QUALITY,
accept nothing less!

Mounting Kit

No additional
adapters, foam, pins,
or no kit at all

No Drain Fitting

Just a plug