

## **CONDENSER 9241414**

## KENWORTH/PETERBILT CONDENSER PRODUCT NOTE

Check the condenser bottom bracket as compared to the unit removed from the truck. If the removed unit looks like the unit shown in the below photo, proceed to check the truck for hood brace clearance with the hood closed and the old unit bolted in position. If required cut and notch the replacement bracket accordingly.

